



Vehicle Technical Inspection Form

NISSAN Pathfinder



Type of car	NISSAN Pathfinder
Type of body	4x4 SUV
Year of product	2008
Fuel	Diesel
Color	Blue
Vehicle Chassis No	VSKJVWR51Z0336515
Mileage	114 423 KM
Engine	Good (Should be checked)
Suspension	Good
Brakes	Good
Battery	No
Fuel System	Good
Tires	Used
Hand brake	Good

Visual inspection of vehicle:

- The vehicle is damaged (rolled over in a ravine). Front bumper, bonnet, front LH light, grill bar, doors, rear bumper and rear lights are damaged. Trunk RH side window broken
- Interior dirty

Remarks:

Gear Box removed (Oil leaking from differential transfer box)
Fuel level Sensor and Fuel Pump removed (damaged)
Pan assy oil removed (damaged)
FM Radion damaged
Door inner handle broken
Steering column needs to be be replace

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 13.06.2013 at 112 421 KM

Accident history:

- At the moment damaged

Required repairs:

Require thorough repairs









